


7 WINDOW INTO HALL
WINDOW INTO SINGLE H
DOWN TO SINGLE GARAGE

8) KITCHEN
SINGLE LIGHT CASE
PITCHED ROOF / LINB FLOOR
SERVING HATCH

9) LANDING
SINGLE WINDOW
ENTRANCE TO BED, LAND + KITCHEN.
CUPBOARD - ROOF SPACE OPEN

10) EXTEN BEDROOM
2 WINDOWS - 1 MUL, 2 LIGHT, 1 CASEMENT (TOP)
PEAK WALL - CUPBOARDS - SERVE HATCH. - BLOCKED FIREPLACE
SKIRTING



Styach

newbold. Exc
 kitchen St DBA
 " " Eval.
 Pickford St DBA
 Crumpton DBA
 Oak Mill DBA
 " " Exc
 Duens BS
 St James BS
 IVES BS
 Worsley DBA
 Worsley BS.

~~028, 030, 035, 036, 037, 038, 031~~

11 - LOWER STAIRWELL.

12 - GARAGE

double garage + single

corrugated plastic roof, concrete floor

sash window. + casement.

brick pillars.

13 - corridor

stone + brick walls

window onto out

stone tacking

flagged floor.

14 kitchen.

sash + casement (inner open) - miss mull.

lino floor.

alcove - dado start cornice hidden beam.

plaster - wallpaper.

15 Hall (bottom)

5 doors - bath, cub, litch, porch, from hall.

carpet

16) Bath.

1 mull window, lino, top case -

17) Cupboard.

18 - front hall

- Stained blocked
- porch. inner door

19 - small sit -

blocked fire place

1 window - min casement - blocked alcove

20 - front sit

1 large wood min - 3 light. - sash

blocked fire place

Skirt + cornice

blocked alcove


21) octagon

2 panelled, wood min, 2 light - front not open casement
fire place - replacement

4 alcoves

dado, cornice + skirt

1ST FLOOR



- All doors 20" in replacement

- 1) OCTAGON BED - HORSE HAIR PLASTER ON FIRE WALL.
3+ SINGLE LIGHT (1 DOUBLE NO MULL) CASEMENT
SKIRTING + CORNICE FLOOR BOARDS
FIRE PLACE
MOLDED DOOR, STRIP LIGHT.
DOWNSTAIRS FLUE


- 2) TOILET
SMALL SINGLE LIGHT (ABOVE PORCH).
SKIRTING
PIZZED CEILING - STUD FRONT.

- 3) SKIRTING
FLOOR BOARDS
WINDOW


- 4) BEDROOM.
1 FIREPLACE (BLOCKED)
1 CASEMENT WINDOW
WITH MISSING MULL.
PIZZED ROOF

- 5) BEDROOM
1 WINDOW CASEMENT.
SKIRTING

- 6) BATHROOM
1 WINDOW SINGLE CASE



GARDEN COTTAGE EXTERIOR



1	SW ELEVATION	N
2	" "	NE
3	" "	NE
4	" "	NE
5	" "	NE
6	" "	N
7	" "	N
8	SW ELEVATION PORCH WAY	NE
9	" " "	NE
10	MULLIONED WINDOW + CELLAR LIGHT WEST END OF SW ELEVATION	NE
11	" " " " " "	NE
12	NW ELEVATION OF PORCH ON SW ELEVATION	SE
13	" " " "	SE
14	CHIMNEY AT WEST END OF SW ELEVATION.	N
15	PARAPET AT EAVES, WEST END OF SW ELEVATION	N
16	" " " "	NE N
17	IRON DEC, SW CORNER	E
18	NW ELEVATION.	E
19	NORTH END OF NW ELEVATION	E
20	" " "	E
21	MUL WINDOW, NW ELEVATION + CELLAR LIGHT (SOUTH END)	SE
22	DETAIL OF CELLAR LIGHT, NW ELEVATION	SE
23	" " "	SE
24	NW ELEVATION, DOORWAY EXTENSION	SE
25	NW EXTENSION, GOTHIC WINDOW	SE
26	NW ELEVATION, SOUTH END.	S
27	" "	S
28	DETAIL, NW ELEVATION, FORMER PITCH ROOF	SE
29	" " "	SE
30	NW ELEVATION	SE
31	" "	SE
32	NE ELEVATION, SINGLE STORY	S

33	NE ELEVATION, GARAGE	SW
34	 	SW
35	DETAIL OF CHIMNEY, NE ELEVATION.	S
36	NE ELEVATION	SE
37	" "	SE
38	SE ELEVATION	W
39	 	W
40	PORCH, SE ELEVATION	NN
41	" "	NN
42	PORCH FINIAL, SE ELEVATION	W
43	NORTH END OF SE ELEVATION - PRIVY	N
44	" "	N.
45	DETAIL OF PLINTH, SE ELEVATION TOWER.	SW.
46	" "	SW
47	TOWER JOIN, SE ELEVATION	SW.
48	 	SW
49	AIR VENT AT BASE OF SE ELEVATION.	NW
50	DRAIN AT NORTH WALL OF PORCH, SE ELEVATION.	N
51	DETAIL " "	N
52	SE ELEVATION, MISSING MULLION, NORTH END (WING).	NN.
53	TOWER OF SE ELEVATION.	SW

1-24

S3-19

23

GAZ

1 Garden Cot	33 Fountain
2 Kitchen garden	34 URAB UPPER TERRACE
3 bound wall	35 Fountain MAIN TERRACE
4 Slip Guard	36 Lamp THIRD TERRACE
5 Footpaths	37 Lake Rd LO FOUNTAIN
6 Potting shed	38 Grotto LAKE SIDE
7 Glass houses	39 Bathhouse ROSE GARDEN
8 Bothe	40 Scout camp. LAKE
9 Sheds	41 Memorial SCOUT HOUSE
10 Stables	42 Memorial SCOUT HUTS
11 Entrance Rd	43 Camp fire CTR. PARK
12 Nursery	44 Miscellaneous MIS. STONE
13 Well	45 WATER
14 Water Pump	46
15 Canal FP	47
16 Lakeside FP	
17 Middle Wood FP	
18 Garden Centre	
19 New Hall	
20 Carriageway	
21 T shaped } Hall	
22 L shaped }	
23 Entrance gates	
24 Square - MW	
25 Rec + Enclo MW	
26 Ice house	
27 Pump House	
28 Stables?	
29 Footbridge	
30 Steps	
31 Retaining wall	
32 Bunker	

GAZ

1 Garden Cottage	34	Secret Maps
2 Walled Garden	35	
3 Boundary wall	36	
4 Slip garden	37	
5 Foot paths	38	
6 Potting shed	39	
7 glass houses	40	
8 Bothe	41	
9 Sheds	42	
10 Stables	43	
11 Entrance Rd	44	
12 Nursery	45	
13 Well	46	
14 Pump	47	
15 ^{Canal} Lake side path	48	
16 ^{lake side} middle wood path	49	
17 middle wood path	50	
18 Garden Centre		
19 New Hall		
20 Carriage way		
21 'T' shaped structure	} @ hall.	
22 'L' shaped.		
23 Entrance Gates		
24 Square Struc (wood)		
25 Rectang (wood)		
26 tree circle		
27 Ice house		
28 Pump house		
29 Stables		
30 Footbridge		
31 Stepped path		
32 Retaining wall		
33 Bunker.		

chamber

WALLED GARDEN


SE

- 1 doorway into garden, through western wall
- 2 N end of gardens, W wall
- 3 detail of stone jamb in walls W wall
- 4 View of " "
- 5 View of doorway in W wall, leading out of garden.
- 6 Inner face, of N end of W wall.
- 7 " " of N wall (S half)
- 8 detail of stone jamb on inside of N wall
- 9 NW corner of walled garden.
- 10 brickwork @ W end of N wall, outer face
- 11 N elevation of potting sheds/stores
- 12 detail of potting shed window, N elevation ^{W pitch elevation}
- 13 detail of potting shed. window, N elevation
- 14 doorway into potting sheds
- 15 detail of stone jamb, entrance to potting shed.
- 16 entrance gates into potting sheds
- 17 view of S elevation of Botre + greenhouses
- 18 Interior view of potting sheds + W end. detail of doorway
- 19 detail of doorway into shed/stores
- 20 detail of stone jamb " "
- 21 view of interior sheds + W end of row.
- 22 detail of interior door in sheds
- 23 Interior of shed
- 24 " "
- 25 doorway into stores
- 26 Interior of stores
- 27 " "
- 28 " "
- 29 Interior of stores - E end
- 30 detail of doorway E end

E
NE
NE
NE
NW
NW
NE
NW
SE
S
SE
E
SW
W
NW
N
NE
NW
E
NE
W
W
W
W
E
E
W
W
E
E

31	doorway, centre of N elevation	
32	" "	SW
33	W end of potting sheds - N elevation	SW
34	E " "	W
35	detail of doorway, E half of N elevation	E
36	View of rear tunnel entrance into greenhouse chim	S
37	detail of _____	N
38	" "	N
39	E end of potting shed, N elevation	N
40	E end of sheds - N elevation	SE
41	double doors @ E end of shed N elevation	SE
42	" "	SW
43	gate at E end of sheds into walled garden	S
44	detail of join between garden wall + sheds	SW
45	View of sheds @ E end of walls N elev	SE
46	View of house + Greenhouse in yard outside N	NW
47	Garden entrance + E end of N elevation	S
48	View of northeast corner of walled garden	SW
49	View of N elevation of W garden	W
50	View of outer wall, north - E corner	NE
51	View of garden entrance @ N end of E elev	NW
52	View of E elevation (N end) garden wall	SW
53	View of central entrance through E elev	SW
54	" "	NW
55	View of central entrance through E elev	SW
56	detail of ↗	W
57	detail of stone jamb ↗	NW
58	View of S end of E elevation inside yard	SE
59	" "	SE
60	" "	

- | | |
|------------------------------------------------------|----------------|
| tail of wall alter @ S end of E ele | SE |
| er wall, SE corner | SE |
| nd of E elevation | SA |
| tail of | SAV |
| " | SW |
| tail of stone post @ South East corner of inner wall | NW |
| end of S elevation | N |
| entral gate into garden through Selera | N |
| SW quadrant of garden showing central E/W wall | N |
| " | N |
| " inner face of W elevation. | N |
| detail of inner, W wall, GC in back | N |
| W end of S elevation | N |
| " | N |
| Stone post @ SW corner of garden inner wall | N |
| detail of | N |
| outer face of W elevation + garden wall of GC | N |
| " | N |
| " | N |
| main entrance to garden from GC | N |
| entrance way @ W end of gardens central divid wall | N |
| Central divid wall | N |
| Side of central wall showing central entrance | N |
| Central + inner face of E elevation | N |
| W end of central wall | N |
| double entrance through central wall | N |
| detail of W end of central wall | N |
| detail of thicketings former Peach + Camellia hedge | N |
| Central + E elevation wall | N |
| Entrance in central wall | N |
| detail of " | N |



CELLAR

25	B1, STAIRWELL TO BASE	NW
26	B2, FROM STAIRWELL (B1)	SW
27	B3, CELLAR LIGHT, NW WALL	NW
28	B3, SE WALL DOOR TO B2	SE
29	B4, NE WALL, DOOR TO B2	NE
30	B4, NN + SW WALL, BLOCKED CELLAR LIGHT,	SW
31	B2,	SW
32	B2	NE

ATTIC

A1, DOORWAY TO STAIRWELL

FIRST FLOOR

BB

ROOM LIST.

CELLAR - B1 - STAIRWELL

B2 - CORRIDOR.

B3 - NORTH ROOM (REAR)

B4 - SOUTH ROOM (FRONT)

GROUND G1 - PORCH

G2 - HALL WAY

G3 - OCTAGON ROOM

G4 - FRONT ROOM - DINING ROOM

G5 - REAR ROOM - SITTING ROOM

G6 - REAR HALL WAY

G7 - CUPBOARD

G8 - BATHROOM

G9 - KITCHEN

G10 - GARAGE

G11 - CORRIDOR

G12 - PRIVY.

G13 - BOILER

G14 - STAIRWELL (LOWER)

FIRST - F1 OCTAGON BEDROOM

F2 WC

F3 HALL

F4 FRONT BED

F5 ~~REAR~~ BED CENTRAL

F6 BATHROOM

F7 UPPER STAIRWELL

F8 KITCHENETTE

F9 CORRIDOR

F10 BEDROOM (WING) REAR.

200

70

80


x00

x80

430

2

0161 789 3078 Birchall Grange Farm.
Jean



GATES + QUADRANT WALLS


- GRADE II LISTED, SEPTEMBER 1987.
- BUILT IN 1850 BY COTTOM + HALLEN OF LONDON, PROBABLY TO A BLORE DESIGN
- DOUBLE CARRIAGE GATES FLANKED BY SMALLER PEDESTRIAN GATES,
- WROUGHT IRON SCROLL WORK WITH BAROQUE STYLE SCROLLED HEADS + ASHLAR WALLS.
- WON AWARD WHEN EXHIBITED AT THE GREAT EXHIBITION OF 1851
- MOVED IN MID 1960'S DUE TO CONSTRUCTION OF M62/63.

ICE HOUSE

- GRADE II LISTED, JULY 1966.
- BUILT IN 1840'S FOR THE 1ST EARL OF ELLESMERE.
- CUP + DOME OR 'GLOBE SHAPED' DESIGN.
- HAMMER DRESSED STONE ENTRANCE, LEADING TO BRICK VAULTED APPROACH CHAMBER/TUNNEL, LEADING TO DEEP ICE CHABER. (BARREL)
- EXPENSIVE CONSTRUCTION - ONLY AFFORDED BY THE RICH.

CIVIL DEFENCE BUNKER

- CONSTRUCTED IN 1951 BY THE WAR DEPARTMENT AS AN ANTI AIRCRAFT OPERATIONS ROOM. OPENED IN 1952 + SERVED THE MCR GUN DEFENDED AREA.
- BUILDING BECAME REDUNDANT IN 1958 RE-USED AS A ROYAL NAVY FOODSTORE UNTIL 1961.
- PURCHASED BY SALFORD CORP + USED AS A JOINT ~~CONTROL AREA~~ AREA CONTROL WITH LANC COUNTY COUNCIL.
- 1968 DISBANDING OF CIVIL DEFENCE CORPS. BUNKER HANDED TO GMCR FIRE SERVICE.
- EARLY 1990S SOLD TO LOCAL GUN CLUB + USED AS A SHOOTING RANGE.



GARDEN COTTAGE

- ~~1~~ Southern elevation SW elevation NE
- ~~2~~ " " " NE
- ~~3~~ " " " N
- ~~4~~ View of entrance porch, SW elevation NE
- ~~5~~ Detail of stone multi window, SW elevation NE
- ~~6~~ " " of entrance porch SE
- ~~7~~ Detail of chimney @ western end of SW elevation N
- ~~8~~ Detail of - parapet? - SW elevation NW
- ~~9~~ View of join between SW + NW elevation NE
- ~~10~~ View of NW elevation NE
- ~~11~~ View of N end of NW elevation NE
- ~~12~~ Detail of gt window @ W end of NW elevation E
- ~~13~~ Detail view of grate + Cellar light ^{garden} E
- ~~14~~ Detail of later insert door, N end of NW elevation E
- ~~15~~ Detail of gt window - N end of NW E
- ~~16~~ View of W end of NW elevation S
- ~~17~~ Detail of former roof line of garage SE
- ~~18~~ View of N end of SW elevation SE
- ~~19~~ View of garage NE elevation S
- ~~20~~ " " " " " SW
- ~~21~~ View of back chimney @ NE gable end of cot S
- ~~22~~ View of NE elevation SE
- ~~23~~ View of SE elevation W
- ~~24~~ Detail of porch on SE elevation W
- ~~25~~ Detail of Chimney at S end of SE elevation SW
- ~~26~~ Detail of join between Cottage + wall, SE elevation NW
- ~~27~~ Detail of plinth, SE elevation SW
- ~~28~~ Detail view of join in SE elevation SW
- ~~29~~ " " " " " SW
- ~~30~~ Detail of plinth + drain, SE elevation W

- | | | |
|---------------|--------------------------------------------------------|---------------|
| 31 | detail view of drain (ceramic) SE elevation | SW |
| 32 | detail of stone window with missing mull, SE ele | NW |
| 33 | View of Octagonal tower at S end of SE el | SW |
| <hr/> | | |
| 34 | Entrance - steps to cellar | NW |
| 35 | bottom of steps into cellar. | SW |
| 36 | gen view of cellars north room. | NW |
| 37 | "gen view of entrance out of north room | SE |
| 38 | gen view of South room | SW |
| 39 | " " | S |
| 40 | View of south end of cellar corridor. | SW |
| 41 | View of north end of cellar corridor + entrance | NE |
| <hr/> | | |
| 42 | View of corridor + entrance door from NW elev | NW |
| 43 | Stairwell from GF to FF | SE |
| 44 | N wall of garage | NE |
| 45 | E wall of garage showing kitchen wind + corridor privy | SE |
| 46 | E wall of garage ——— wind + door. | SE |
| 47 | S wall of garage showing doorway to stairwell | SW |
| 48 | S end of N wall of garage | NW |
| 49 | N end " " | NW |
| 50 | roof of garage. | SW |
| 51 | flagged floor of corridor between NE gable + privy | SE |
| 52 | detail of " " " " | SE |
| 53 | View of corridor | SE |
| 54 | roof of corridor. | SE |
| 55 | Plinth on NE gable end in corridor. | SW |
| 56 | N wall of kitchen | NE |
| 57 | N + W wall of kitchen | NW |
| 58 | S + W wall of kitchen | SW |


59	S wall of kitchen	SW
60	S + E wall of kitchen.	SE
61	E wall of kitchen.	NE
62	Detail of Arga, N wall of kitchen.	NE
63	Gen view of bathroom	SW
64	View of rear hallway + entrance to garden	SE
65	View of Cupboard door @ W end of rear hallway	NW
66	Interior of Cupboard.	NW
67	Detail of safe within cupboard.	NW
68	gen view of hallway (north end)	SW
69	" " " " (south end)	SW
70	gen view of hallway north end.	NE
71	Detail of former/blocked stairwell + bannister posts.	NE
72	" " " "	NE
73	View of small rear sitting room N wall sitting	W
74	" " a blocked FP in dining room (W wall)	NW
75	View of E wall of dining room.	SE
76	Stone mull wind, S wall of dining room	SW
77	blocked FP, W wall of dining room.	NW
78	Partition wall between dining + sitting.	NE
79	E wall of dining room, door to hall.	SE
80	Light surround, dining room Ceiling Rose	SW
81	Ceiling rose.	NW
82	Ceiling of dining room	/
83	Cupboard doors in front hall way	SE
84	Entrance door to octagonal sitting room	NW
85	Alcove in octagonal room	NW
86	Fire place in octagonal room	NE
87	Alcove, octag.	NE
88	Panelled, stone mull window in octag	SE

89 Alcove	SE
90 Panelled window,	SW
91 Ceiling rose, Octagonal room	SW
92 Entrance Porch	SW
93 " "	SW
<hr/>	
94 Fire place, first floor octag bedroom	N
95 Detail of " "	N
96 Octag bedroom windows	SE
97 Octag bedroom doorway + window	W
98 WC (1st floor) above entrance Porch / hallway	SW
99 1st floor, front hallway	NE
100 front bedroom	SW
101 Entrance into front bedroom + east wall	NE
102 blocked fp, front bedroom	W
103 1st floor, rear bedroom, W wall	NW
104 Entrance (doorway), E wall of rear bedroom	SE
105 1st floor bathroom, E wall	E
106 1st floor kitchenette, E wall	E
107 " " "	E
108 1st floor, rear corridor, leading to kitchenette + rear bed	NE
109 N + E walls of rear bedroom	NE
110 W wall of rear bedroom	SW
111 S wall of rear bedroom	SW
112 Roof hatch above kitchenette	SW
113 Upper staircase	NW
<hr/>	
114 Doorway into Octag attic room	NW
115 N wall of Oct attic room	NW
116 Window in N wall of attic room	N

- ~~117~~ S wall of Oct room showing window
- ~~118~~ Disused gas lamp fitting @ entrance to attic
- ~~119~~ Detail of N wall window
- ~~120~~ Roof space next to Oct room

~~SW~~
~~NW~~
N

— SW




STABLES.

- | | | |
|----|-----------------------------------------------|----|
| 1 | South gable end of stables. | NW |
| 2 | Southern bay of stables. | NW |
| 3 | Interior of Southern bay. | NW |
| 4 | Partition wall between N + S bays, hay loft | N |
| 5 | Elevation of stables, showing driveway + wind | NW |
| 6 | N end of E elevation | NW |
| 7 | E elevation | SW |
| 8 | later insert window, N end of E elevation | N |
| 9 | E elevation | NW |
| 10 | roof interior, beams + joists | NW |
| 11 | N elevation | S |
| 12 | Window @ N end of W elevation | NE |
| 13 | W elevation | SE |
| 14 | " " " " | SE |
| 15 | Detail of brickwork, W elevation | SE |
| 16 | " " " " | SE |
| 17 | Slate roof of stables. | E |
| 18 | Eaves + purlins on N gable end. | S |
| 19 | Drainpipe N gable end. | SE |
| 20 | Detail of eaves, N gable end. | SE |

BARN

- 1 Southern bay of barn. - N
- 2 " " " - E
- 3 first floor of barn - NN
- 4 " " - E
- 5 " "
- 6 roof of barn - N.
- 7 office at southern end of barn - S
- 8 roof truss - SW.
- 9 " " "
- 10 Southern + eastern elevation of barn - NW
- 11 South Elevation - N. (Gable)
- 12 Gate post recessed into southern gable - N.
- 13 South + W elevation - NE
- 14 West Elevation - NE
- 15 detail, ground floor window - E
- 16 north + west elevation - SE
- 17 " "
- 18 modern ext about N gable.



BUNKER

1	EAST END SOUTH ELEVATION	N
2	SOUTH ELEVATION PORCH.	NW
3	" "	NW
4	DOORWAY SOUTH ELEVATION	NW
5	" "	NW
6	WEST END SOUTH ELEVATION	N
7	SOUTH ELEVATION PORCH.	NE
8	WEST FACE ELEVATION.	NE
9	" " " - southern end	E
10	WEST ELEVATION - northern end,	SE
11	ROOF CLOSE UP <u>detail</u> .	SE
12	" "	SE
13	NORTH ELEVATION - western end.	E
14	AIR VENT NORTH ELEVATION	S
15	NORTH ELEVATION DOORWAY	SE
16	" "	SE
17	NORTH ELEVATION PORCH LIGHT	SW
18	CLOSE UP NORTH ELEVATION DOOR	S
19	NORTH ELEVATION - eastern end,	W
20	EAST ELEVATION.	W
21	STEPS AT SOUTHERN END OF EAST ELEVATION.	SW
22	AIR VENT EAST ELEVATION	W
23	STEPS AT EAST END OF ^{SOUTH} NORTH ELEVATION	N
24	" " " "	N
25	FABRIC DETAIL DOOR SOUTH ELEVATION	N
26	" " " "	N

ICE HOUSE

1	NORTH ELEVATION OF ENTRANCE	S
2	" "	SE
3	CLOSE UP NORTH ELEVATION	S
4	" " " ROOF	S
5	INSIDE EAST WALL	SE
6	ENTRANCE INTO VAULT	S
7	WEST WALL + DOOR TO VAULT	SN
8	FLOOR OF ENTRANCE - 8 steps	S
9	GRAFFITI	W
10	INNER DOORWAY	S
11	" " "	S

GARDEN COTTAGE

CELLAR

B1 - STAIRWELL

B2 - HALLIDOR

B3 - OFFICE 1 - NORTH

B4 - OFFICE 2, - SOUTH

G1 - FRONT PORCH/EN

G2 - FRONT HALL

G3 - OCTAG

G4 - DINING

G5 - SMALL SITTING

G6 - BATHROOM (GF)

G7 - LEAK HALLWAY

G8 - CLIPBOARD

G9 - LEAK PORCH,

G10 - KITCHEN

G11 - GARAGE

G12 - PRIVY CORRIDOR

G13 - PRIVY

G14 - LOWER STAIRWELL

BOTHE

G1 - BEDROOM 1

G2 - SITTING ROOM

G3 - UTILITY ROOM

G4 - ENTRANCE HALL

G5 - BEDROOM 2

G6 - KITCHEN

G7 - LIVING ROOM

F1 - UPPER STAIRWELL

F2 - FIRST FLOOR HALLWAY

F3 - BATHROOM

F4 - BED 3

F5 - 11 4

F1 - WC

F2 - HALLWAY FRONT

F3 - OCT BEDROOM

F4 - SOUTH BED

F5 - ~~KITCHEN~~ BED

F6 - BATHROOM

F7 - UPPER ST

F8 - REAR HALL

F9 - KITCHEN

F10 - NORTH BE

Trench 1 Forties


0 2 1001

Room 1

2

3

4.



① N-S Aligned Stone Built Wall
Full L+W+D Not Established

135 x 40 x 40 Exposed
2 Courses Visible

Block sizes 0.40m (L) x 0.16m (D) x ? W

Various 0.28m x 0.14m x 0.14m

0.43m x 0.16m

About North face of ②

• East face is exposed - likely to
be facing outside.

② External stone wall

West wall of entrance.

② E-W Aligned External Stone

Wall, Not fully exposed

$3.40\text{m (L)} \times 0.60\text{m (W)} +$

Excavated to a depth of 0.57m

Made of Very Large ^{SAND} Stone

Blocks Over $1.50\text{m (L)} \times 0.26\text{m}$
wide + 0.30m (D)

The North face is an external face with Ross Rustication.

- forms a corner with ①.

• Wall continues E & W into Treasury
Brick

• The South face of wall is


Clay with a single string of brick
and stretchers to stretch.



Brick Size 0.24×0.7

$\times 0.10\text{m}$

At the East end of ② wall is stepped up by 0.23m. May Threshold for Entrance Door Not Completely Visible



A Possible Slot for a 'Runoff' Pipe has been cut through ② of 0.20m (w) located directly above drain ①. Now Blocked by Brick

③ N.S. & Aligned Breach and
Stone Wall.

(w) (b)
or $1.75m (4) \times 0.56m \times 0.20m$

~~Chap~~ B HMB on the

East face. STONE ON WEST FACE

A Soft Lime Mortar used to


Set the bricks.

x2

The wall has used 5 Stone Blocks
of various sizes in its construction

$0.97m \times 2.0m \times 2.0m$

$0.58m \times 2.0m \times 2.0m$




Bricks have been cut to
fit Round Stone

③ CREATES A DIVISION BETWEEN
CELLS 4 & 5.

(10) - $154m \times 0.70m \times 0.40m$ (10)
Exposed To 5 Courses.

E-W Aligned
H.M.M. WITH STONE CLIPPING ON
NORTH FACE (SAME AS (3))
3 Brick STRENGTH
Brick Size = $0.23 \times 0.10 \times 0.07m$
WHITE Lime Mortar



- THE EAST END OF (10) FORAYS 4
1.17m GAP WITH THE WEST END
OF WALL (6)
- THE WEST END OF 10 HAS
BEEN BUILT ON AN ANGLE

CREATING A POSSIBLE WINDOW BAY.

- ④ A PARTIALLY DESTROYED
VAULTED ROOF (SPRING ARCH).
SPRINGING FROM INTERNAL FACES
OF WALLS ② TO ⑩



HANDMADE BRICK.

ONLY 4 STONES SURVIVE
ON THE SOUTHERN SIDE

THE ROOF HAS BEEN ~~REMOVED~~
SPRINGING FROM SPECIALLY SHAPED
STONE BLOCKS ON WHICH
THE BRICKS ARE Laid




BRICKS ARE Laid STRUCTURED TO
STRENGTH SET WITH A HARD
CONCRETE LIKE MORTAR.

THE ROOF AREA MEASURES

158m (N-S) x 0.90m (E-W)

Infill of Celfar Ru 1316

⑤ HMB Floor of Ceiling
of Room ④



Constructed from

ALTERNATING HEADERS

15 REINFORCES

HARD WHITE LIME MORTAR

16 STRENGTHS SURVIVE MOSTLY

IN THE NE CORNER

2 ~~BRICK~~ BRICK COURSES THICK

CONTINUED BY WALLS ③+②

⑥ - N/S Aligned ~~At~~ HMBW(1).

0.56m (w) x 2.70m (2) x

0.46 (o) D & L Not fully

Ex. Wall continues into

N/S Trench BACKS

6 COURSES DEEP

East Side is PLASTERED (Rough 2)

4 STRINGS WIDE 0.24 x 12 x 7


OCCASIONAL BRACKLE 0.13 x 10 x 7

(REUSED?) HAVE

0.12 x 0.09 x 0.07

BEEN USED IN THE CONSTRUCTION.

ESP AT THE NORTHERN ENDS



THE ~~ST~~ SOUTHERN


END HAS BEEN

THICKENED TO

0.80m WIDE TO CREATE

AN ENTRANCE WITH

OPPOSING WALL (10)



(9) The 3 walls of Room 1.
Hyp. B. Plastered on every
internal face. Very thick
(3cm)
Excavated to a max of 10 courses


Bricks laid stretchers to stretchers

Walls are clearly internal
Being only x 2 courses wide
 $0.23 \times 10 \times 7$
 $0.16 \times 10 \times 7$
 $0.13 \times 10 \times 7$

A possible entrance is located
along the north wall. Now
blocked by large pieces of masonry
- 1.20m wide. with signs
of a timber door frame ~~at~~
South face of bricks.

Another potential entrance
located in the ~~stair~~
SW corner with wooden
framing present on S & South
face of Bricks.

Also electrical wiring
present in Cased in Fe Pipe



General Trench Info.


Top soil: Tree Roots + Grass

Garden Soil: - 0.30

Rubble - Bricks - - 0.25 m


Top soil 47.

Rubble 46




Trench Dug to max of 1.40 m

⑪ Stone Capped Brick Drain.




Roughly Cut Sandstone

located Below Cut for
drain pipe running through
cut in wall (2).



Excavated to a depth of 0.80m
HMB = 23'12" x 0.07' (116)

TRENCH 2



⑫ E-W Aligned Thick Brickwork.
Northern wall of Basement.

Max width = 1.10m - 5 strings

Length - 2.60m


Excavated to a full depth of

2.70m where a brick floor

was exposed in Southern

Basement. Now infilled to a

Depth of 1.10m - (16 courses)



Mortar is a soft limey

- The remains of a N to S Spring Arch is present on the top 2 upper courses, where Bricks have been set @ Stretcher to stretcher on an angle.

48 - Backsurface in TR2

13 - N-S Aligned HMB
Abuts S face of 12
Seen only in section

1.50m (L) x 2.70m (D)



Abutted by 26

East wall of Cellar (South)

14 - West wall of South Cellar

C N-S Aligned
Poor survival

Only 0.65m (L) remains
Ex to a depth (Max) of 2.70m

Abuts 12

SOUTH CEILING TR2



(B) Vaulted Roof Spanning
E-W Gray Wall (B) to
an Unseen Wall to the East not
SEEN in EXCAVATION

HMB Laid EDGE ON STRECHER
TO STRECHER.

Concrete Hard white mortar

(16) E N-S Aligned wall
Overlying + Banked to top of
Vaulted ceiling (15) +
North face of (12)
x 2 starts wide (1 Brick length)
1.70m in length but Proj & Tended
to length of (15)
Base
Integral wall from Floor 1?

(17) N-S Aligned 0.70m wide
Wall
Foundation for 1st floor wall?
3 Brick lengths wide
(17) Narrows after x 2 courses (0.20m)
to become a 0.36m wide
Integral wall
Mortared brick concrete.

①7 ~~abutt~~ abutts Phase ①
Wall ①8.

①7 Overlies Vaulted Ceiling ①5

①8 Phase ① - External N-S
Aligned Wall. Stone facing
on East face.
Phase ② Wall ①9 Abutts
its East face.

Vaulted Phase ② Vault
①5 has been sprung from
this external Wall.
originally

Wall ①2 Abutts East face
of ①8 - Proving they are
contemporary.

only 013 - Visible in width.

The wall is clearly shown in
Underground picture of Northteen
Cellar - being re-used' as west
wall.

(P2)

(20) Reused refractory bricks
carrying a Radio type flooring
outside phase (2) extension
of cellar.

1 course thick - $16 \times 0.05 \times 0.06$
Laid edge on.

Partially destroyed
Overlies stone foundation
layer (21)

(20) Extends both E + W into
Trench bank.

It is likely that 21 + 20

Originally extended Norwards
for approx 2m, and stopped in
line with a stone wall

Structure seen in west
facing section.

- Hard Core

(23). Stone levelling layer
ass with Phase (2) Extension
Underlies Paving (20) + Stone
Foundation (21)
level layer for a Paving
Embedded originally to same
Point as 20 + 21

Sandstone

(24) Grass Slightly loose band
Core levelling layer to

23 Underlies (23)

Crushed Sandstone

Occasional Brick

Small Stones - Compact Red

(25) Possible interface between
levelling layer 2A + Natural
sandstone deposits
Contains large boulders
Extends width of trench.

(26) Concrete blocks at the
North end of Trench
Directly underlying Roots
Overlying a
Brown grey gravelly
Sand levelling deposit
Extent - unknown
0.08m thick


0.60 x 3m exposed

During excavation Starling

Associated with

later occupation

of the site in WW2? Road?





30. - ^{Internal} N-S Aligned Way
x 2 Brick 57cm wide
Abutted by wall 31
Excavated to a depth of 0.50m
(5 courses)

Degraded mortar - Pinky
Bricky, sandy lime
Way is in a fairly good
State of Preservation.
Slight damage caused by
falling debris [33]

Plaster on both E & W faces,
Paving Rooms (in ~~terminal~~ Brick
walls)

It is bonded to 31

~~Bonded~~ Bonding not clear due
to plaster on both faces.

Brick size - $23 \times 12 \times 0.7m$
5mm wider than those Bricks
found in TR 1 and 2.

Plaster: 3cm thick.

Along length of JO is a possible
in built fireplace - note blackened
Bricks & West face.

Apex 130mm wide


Walls have been thickened to
0.55m either side of fireplace -
forming reinforced brick
stations'.

The central back wall of string
FB is only 1 Brick ~~thick~~
wide (0.12m)

Central Ave is 0.55m
wide


This feature may be the top
of a chimney flue from a fireplace
located below in the basement
Room.

0.48m of L bricks exposed.



(3) E-W Aligned wall bonded
to west face of (30).
A Mock thickened wall.

Contains 3 Square cuttings



(9 courses)

Same pinky lime sandy mortar as
30.

Possible heating system.
or Building style - a way
to use less bricks.

Wall extends in to west section,

Plaster of N+S faces.

(33) Fallen masonry located in

Site near westerly Room

$30 \times 25 \times 27$

$60 \times 40 \times 30$

$30 \times 26 \times 15$

$40 \times 40 \times 20$

$65 \times 40 \times 15$

[Some fixed
with copper strips]

Large pieces of sandstone

Blackening on out-facing

dressed stone

Carved stone

Exterior stone

decorated

Chimney pots from exterior

wall.

(34) Brick Rubble

(35)

Possible door/window frame

$0.4 \times 0.07 \times 0.13$

(36)

Layer of Chinkert, possible
ass with building on
Bunker
0.12m Thick


Used as a leveling surface

(37) Leveling Layer associated
Bunker

Medium angular stones
Compacted
0.25m

Trench excavation to a max
depth of 1.10m

(31) - Possible blocked entrance



Note possible Door Sockets
ON E/W facing posts.

The Mortar used on the blocking
is much ~~less~~ Roughly applied
~~thinner~~ than abutting walls.
Proof of deterioration.

Brick sizes are 0.10/0.11 cm
wide rather than the 0.12 cm
width of Original Bricks.



Terre

510

2.60


2.60

404

38

40

~~38~~ 41



38. Garden Soil

Rich Humic Dark Brown

Contains no stones

freq Root activity

120 (E-W x

Extends to a depth of

0.10 m

39. E-W Aligned Brick wall.

1 Course in Height,

Founded on gravel (0.2m x 0.2m)

3 Shims in. gap (160m)

Extends w to Section

Brick Sizes 0.24 x 0.11 x 0.07

0.24 x 0.11 x 0.07

Located in Between 2 Trees

(Oak + Beech). - at which point

39 is severely damaged by Roob

Runs parallel to 01-10-20

4D

✓

Compacted gravel/surface

large gravel pieces

almost Roughly laid corner

Very Patchy Poor Surface

due to Root action

- is flush with Top of way

almost lies up against

North face of 39.

Only 2cm Thick

Overlies Poor gravel foundation
Surface

Very fragile

Poor Surface

41. Poor Gravel

42. Soil

43. Roof Topsoil

LEVELS

TBM 200

BS 1.23

IH 201.23

-TRENCH 1 -FS

1 1.75 9 2.22

2 1.61 10 1.91

3 2.07 11 2.00

4 2.20 12 2.09

5 1.96 13 2.01

6 1.97 14 2.02

7 3.13 15 1.92

8 3.13 16 2.09

17 1.76

18 1.99

19 2.00

20 2.21

21 2.65

22 2.52

23 1.64

24 1.48

TRENCH 2 - FS

25	1.75	36	1.94
26	1.81	37	1.95
27	2.23	38	1.72
28	2.69	39	1.76
29	2.09	40	1.91
30	1.71	41	1.84
31	1.71	42	1.85
32	1.77	43	1.88 2.00
33	1.67	44	2.23
34	1.93	45	2.47
35	1.87	46	2.38
		47	1.78
		48	1.63

-TRENCH 3

10
long

49	1.97	58	2.68
50	1.98	59	3.52
51	2.60	60	2.76
52	2.50	61	2.76
53	2.80	62	2.88
54	2.71	63	3.30
55	3.00	64	3.24
56	2.56	65	2.79
57	2.66	66	1.99
		67	2.05

-TRENCH 4 LOCATION

SOUTH-WESTERN CORNER

22m FROM WESTERN WALL

END.



← 22m ←